


**ANACONDA Copper Company**

New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



September 30, 1980

Mr. Ed Sandell,  
Deputy Conservation Manager  
UNITED STATES DEPARTMENT OF INTERIOR  
GEOLOGICAL SURVEY  
P.O. Box 26124  
Albuquerque, New Mexico 87125

RE: Jackpile Mine Reclamation Plan  
Report - Second Quarter, 1980

Dear Sir:

In accordance with the Jackpile Mine Reclamation Plan, we submit the following data for the Second Quarter of 1980.

1. Radiological Analysis of Ground and Surface Water.
2. Chemical Analysis of Ground and Surface Water.
3. Maps showing Ground and Surface Water Sampling Locations.
4. Results of the Air Monitoring Program.
5. Results of the Ambient Radon Study.
6. Map showing location of Air and Radon Monitoring Stations.

Sincerely,

A handwritten signature in cursive script, appearing to read "Meade A. Stirland".

Meade A. Stirland, Manager  
ENVIRONMENT, HEALTH & SAFETY

jls

Enclosures